Oil Field Environmental Incident Summary

Responsible Party: HRC OPERATING, LLC
Well Operator: HRC OPERATING, LLC
Well Name: PETRO-HUNT 157-100-1C-1-1SWD

Field Name: DUBLIN Well File #: 90155

Date Incident: 8/7/2015 Time Incident: 03:00 Facility ID Number:

County: WILLIAMS Twp: 157 Rng: 100 Sec: 1 Qtr: SE NE

Location Description:

Submitted By: Julia Traster Received By:

Contact Person: Chris Martinez

1801 CALIFORNIA STREET

SUITE 3500

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 50 Gallons 50 Gallons 50 gallons

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/19/2016 Clean Up Concluded: 8/8/2015

Risk Evaluation:

low human health hazard

Areal Extent:

About 4 feet around offload environmental pot/getty box.

Potential Environmental Impacts:

Salt affected soil on well/facility site

Action Taken or Planned:

T&R Trucking picked up free liquids, put down absorbent materials, and will scrape up contaminated soil. Spoke to truck driver and his supervisor about following established procedures.

Wastes Disposal Location: Wastes will be disposed of at an approved landfill

Agencies Involved:

Updates

Date: 8/10/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 50 gallons of brine was released on the facility site. NDIC retains oversight.